



MI ROOM AFS SOHNA ROAD
CERTIFICATE: DRIKING WATER QUALITY

- 1 Place of water collection - RO system at KV No 02 at 1600 hrs.
- 2 Parameter checked
 - (a) TDS - 72 ppm
 - (b) Chlorination- Nil
- 3 Report - Satisfactory

Place/Unit: 
 Date: 11 Jun 11




 कर्मवीर सिंह
 प्राचार्य/PRINCIPAL
 के. वि. क्र. 2, सोहना रोड, गुरुग्राम
 KV No. 2, Sohna Road, Gurugram
 पिन-122001/PH

